



into the ground up to 44' deep.

The tank bottom, initially installed by another contractor, has failed twice since

Leakage Investigation

Leakage investigation was performed using a variety of methods including:

- Visual inspection
- Infrared thermography
- Ultrasonic testing
- Gas detection
- Soil gas monitoring
- Groundwater monitoring

Results of the investigation are as follows:

1. No leaks were detected during the investigation.